UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,349,226 B2 Page 1 of 3


APPLICATION NO. : 10/638982 DATED : March 25, 2008

INVENTOR(S) : Ice

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 1, replace Figure 1 with the figure depicted below, wherein the connectors **306** have been relabeled **312**




Signed and Sealed this


Fourteenth Day of September, 2010

David J. Kappos Director of the United States Patent and Trademark Office

Sheet 2, replace Figure 2 with the figure depicted below, wherein the channel $\bf 404G$ has been relabeled $\bf 404A$



Sheet 6, replace Figure 4B with the figure depicted below, wherein the channel $\bf 404B$ has been relabeled $\bf 404A$ and the channel $\bf 402B$ has been relabeled $\bf 404A$



Column 6

Line 15, after "400", add [(see FIG. 2)] Line 33, after "300", add [(see FIG. 1)]

Column 8

Line 5, change "302" to --302A--Line 10, change "302" to --302A--Line 46, change "304" to --302--Line 60, after "100", add [(see FIG. 2)] Line 63, change "1100" to --100--

Column 10

Line 30, after "100", add [(see FIG. 4A)] Line 40, change "3101B" to --310B--Line 40, change "3101B" to --310B--

Column 11

Line 6, after "302", add [(see FIG. 4A)]